Shilpa Pharma Lifesciences Limited, Unit 2
Plot No: 33, 33A & 40-47, Raichur Industrial Growth Centre, Chicksugur 584134, Raichur, Karnataka, India
ElA forAO-AO-7 Block

				E	Base Ir	npact		Res	idual Ir	mpact	
No	Activity	Description of Aspects	Consequence (Worst Case)	S		Rating	Existing Impact Control Measures	S	L	Rating	Additional Impact Control Measures
1	Raw materials Handling (Liquids ,Solids ,Semi solids Acids,Base,Pyrophoric,Hygorscopic Chemicals	Environment pollution Hazardous waste generation	Legal Non compliance, Natural resources depilation Work place environment pollution Natural Resource conservation	3	2	Medium	Materials handling in double packing with secondary containment and With pallets Following safe spill control and safe hazardous and Non hazardous waste disposal methods	2	1	Low	Check periodically existing controls and practices Effective training to be provided. Work area monitoring and VOC
2	Processing Raw materials and ingredients as per required for product process flow at production blocks	Environment pollution Hazardous waste generation	Legal Non compliance, Natural resources depilation Work place environment pollution	3	3	Medium	1) Materials handling in double packing with secondary containment and With pallets 2) Following spill controls and Hazardous waste safe disposal procedure 3) Following Consent for operation mention conditions to comply Legal requirements 4) Following safe decontamination & detoxification methods to avoid environment pollution 5) Monitoring ambient air quality parameters to measure environment pollution all parameters are with in limit as prescribed in Consent for operation 6) Online VOC monitoring system available to monitor continuous air quality 7) Following safe effluent collection and treatment system having zero liquid discharge facility to avoid environment pollution 8) Periodical ground water& soil sample, Treated and Raw effluent analysis done by MOEF authorized laboratories all reports are with in standard limits 9) Air pollution control system like scrubbers available to control figurative emissions 10) AHU Filters are available to avoid dust contamination & AHU Filters are disposing after detoxification and cleaning 11) Using natural green energy to reduce carbon emissions.	2	1	Low	1) Work area monitoring and VOC
3	Sample collection & submission of Sample to qc for analysis purpose	Environment pollution Hazardous waste generation	Legal Non compliance, Natural resources depilation Work place environment pollution	2	3	Low	1)Collecting sample bottles to avoid spill and exposure 2) sampling bottles are disposing after cleaning and decontamination	2	1	Low	Effective training to be provided 1) Work area monitoring and VOC
4	Packing of final product	Environment pollution Hazardous waste generation	Legal Non compliance, Natural resources depilation Work place environment pollution	3	2	Medium	1) Trained operators are operating systems with operating procedures 2) Minimsing waste spillage during package 3) Using containment equipment's like Isolators and Clean room system with proper air pollution control system like scrubber to avoid environment pollution	2	1	Low	Periodically required evaluate existing control
5	production equipment's Cleaning	Environment pollution Hazardous waste generation Usage of Natural Resources Usage of electrical Power	Legal Non compliance, Natural resources depilation Work place environment pollution	3	3	Medium	1) Trained operators are handling system cleaning 2)Using appropriate solutions to clean systems 3) Taking measures to avoid spillage ,If spill materials will clean by using spill control kit 4) Spill cleaned materials hand over to Environment department for safe disposal	2	1	Low	Periodically required evaluate existing contro
6	Collection packing storage &disposal of Hazardous waste & Non hazardous materials safely	Environment pollution Hazardous waste generation Usage of Natural Resources Usage of electrical Power	Legal Non compliance, Natural resources depilation Work place environment pollution	4	4	High	a) After proper treatment hazardous waste disposed by Environment department as per Consent for operation conditions b)Employees using proper PPE While handling operations c) Dedicated safe storage facility available to Hazardous waste storage	4	2	Medium	Periodically required evaluate existing control Scope for E-waste management Implementat for E waste Scope of implement biomedical waste management

Prepared By	Cheked By	Approved By
Name::K. Ananda (Dy.Manager)	Name:Lokeswara Duthala (Sr. Manager)	Name: R Elangovan (DGM-EHS)
Sign: (1200 de 25/05/2)	Sign: 4-25 05 13	Sign: Remarks

Shilpa Pharma Lifesciences Limited, Unit 2

Plot No: 33, 33A & 40-47, Raichur Industrial Growth Cent	e, Chicksugur 584134, Raichur, Karnataka, India
--	---

HIRA for Production Department AO-AO7-- Block

					Base I		Tourish Department No see	B	lesidua	Risk	
Sr No	Activity	Description of Hazard	Consequence (Worst Case)	S-1	L-1	Rating	Existing Risk Control Measures	S	L	Rating	Additional Risk Control Measures
1	Raw material receipt from warehouse to block, (Solid RM, liquid ,solvents)	Spillage Exposure Fire	Slip trip fall injuries Facility loss Product loss Occupational Injuries	3	3	Medium	SCBA available for control of Toxic gases control Forklift is used for transfer of solid, liquid and solvent. Fire hydrant and Fire extinguishers available to control fire Fire balls available to control fire	3	1	Low	Effective Training to be provided. Fire detection, alarm system Work area monitoring and VOC and LEL
2	RMs shift to shop floor	Spillage Exposure Fire	Slip trip fall injuries Facility loss Product loss Occupational Injuries	4	3	High	Shifting materials with proper secondary protection & proper packing Two employs are using to lift or shift materials from one place to other place Always keeping house keeping good condition barricading area and use spill control kit to collect spill Sufficient illumination available to avoid slip trip fall Employees using activity related Personal protective equipment to avoid exposure hazard Dedicated storage facility available at diffent mateials at diffent location with adequate safety measures	4	1	Medium	1. Effective Training to be provided. 2. Fire detection, alarm system 3. Work area monitoring.
3	Charging solid &liquid material	Spillage Exposure Static fire Hazard	Slip trip fall injuries Facility loss Product loss Occupational Injuries	3	- 3	Medium	while handling solids proper earthling and bonding is ensured using SS Scoops to control static charges PPE like mask & gloves are used. Effective fire extinguishers are available Emergency exit available to control spill Dedicated eye wash& body wash shower available Eye wash bottles available for eye spill cleaning Fire hydrant system available to control fire Fire balls available to control fire Spot Exhauster system available Dedicated Occupational health facility available Periodically checking earth pit resistance and earthling bonding continuity Block wise earthing bonding continuity testing system available Contentious nitrogen blanketing maintaining	3	1	Low	1. Effective Training to be provided. 2. Fire detection, alarm system 3. Work area monitoring and VOC and LEL
4	Charging fo liquid RM	Spillage Exposure Static fire Hazard	Slip trip fall injuries Facility loss Product loss Occupational injuries	4	1	Medium	To monitor pressure dedicated pressure gauge are available Vent is keeping open condition to avoid pressure build up in system Temperature indicator available to control temperature Based on temperature of reaction mass steam or hot water circulation control by Shift chemist & shift in charge will monitor periodically Using proper equipment with proper pressure control system & Nitrogen for filtration purpose Doing leakage test before start unit operation to avoid spill and leakage Periodical preventive maintenance available to ensure pressure gauges and Temp sensor working and control valves working properly Fire extinguisher and Fire hydrant ,Fire balls available to control fire Spill control system available to control spill	3	1	Low	1. Effective Training to be provided. 2. Fire detection, alarm system 3. Work area monitoring and VOC and LEL

5	Charging of solvents	Spillage Exposure Static fire Hazard	Slip trip fall injuries Facility loss Product loss Occupational injuries	4	3	High	To monitor pressure dedicated pressure gauge are available Vent is keeping open condition to avoid pressure build up in system Temperature indicator available to control temperature Based on temperature of reaction mass steam or hot water circulation control by Shift chemist & shift in charge will monitor periodically Using proper equipment with proper pressure control system & Nitrogen for filtration purpose Doing leakage test before start unit operation to avoid spill and leakage Periodical preventive maintenance available to ensure pressure gauges and Temp sensor working and control valves working properly Fire extinguisher and Fire hydrant ,Fire balls available to control fire Spill control system available to control spill Earthing bonding continuation available	4	1	Medium	Fire detection, alarm system Work area monitoring and VOC and LEL
6	Handling gases & Gas purging to Reaction mass	Spillage Exposure Static fire Hazard Explosion	Facility loss Product loss Business continuity Interruptions Occupational injuries	3	3	Medium	Dedicated gas cylinder storage facility available at site Regular using plant Nitrogen for blanketing If required using Nitrogen gas cylinder for blanketing based on product sensitivity Gas cylinder manifold ,pressure gauges, gas regulators available to handle gas flow During gas purging contentiously monitoring gas flow and pressure by shift chemist till completion of activity	2	1	Low	1. Effective Training to be provided.
7	Dispensing of Liquid RM	Spillage Exposure Static fire Hazard	Slip trip fall injuries Facility loss Product loss Occupational injuries	3	3	Medium	To monitor pressure dedicated pressure gauge are available Vent is keeping open condition to avoid pressure build up in system Temperature indicator available to control temperature Based on temperature of reaction mass steam or hot water circulation control by Shift chemist & shift in charge will monitor periodically Using proper equipment with proper pressure control system & Nitrogen for filtration purpose Doing leakage test before start unit operation to avoid spill and leakage Periodical preventive maintenance available to ensure pressure gauges and Temp sensor working and control valves working properly Fire extinguisher and Fire hydrant ,Fire balls available to control fire Spill control system available to control spill	3	1	Low	Periodically Required to check existing controls and practices Scope to have flow control for solvents pumping from day tank to Reactors & ware house to reactor Reactor solvent dispensing pipe required to extend up to reactor walls to avoid static discharge (J pipe or Dipleg)
8	Charging & Addition of Acidic RMs	Spillage Exposure Corrosion of Equipment's	Slip trip fall injuries Facility loss Product loss Occupational injuries	3	3	Medium	Using work dedicated personal protective equipment's to control occupation Hazards Trained employees handling to safe activity completion Facility compatibility and facility selection process ensure safety of materials and equipment, facility compatibility Online Air breathing system available Dedicated scrubbing system & exhausting system available to control fumes	3	1	Low	Separte plat form to be develop up to manhole to check total tank condition
9	Temperature rising and Maintaining of reaction mass after Acidic liquid RMs addition& maintain production process	Exposure Fire Occupational exposure	Slip trip fall injuries Facility loss Product loss Occupational injuries	3	3	Medium	controlled addition doing based on Reaction mass temperature Dedicated pressure gauges & temperature sensor available to monitor pressure and temperature Trained chemist monitoring system conteniouslyand periodically noting parameters in BPR, Chemist will take control measures if found excess process parameter Condenser vent kept open to atmosphere contentiously to avoid pressure build up in system Dedicated scrubber and spot exhaust system available control fumes	3	1	Low	

10	Reaction mass in process sample collection at -30 & and at210 °c	Spillage Exposure Corrosion of Equipment's Fire	Slip trip fall injuries Facility loss Product loss Occupational injuries Business continuation issues	2	3	Low	Sample collection by using sample collection Rad Spot exhauster system available to control fumes during sample collection Employees using activity bases personal protective equipment's Activity handle by trained employees Spill control kit available to control spill Fire extinguisher & Fire hydrant and fire balls available to control fire Sample collection from reaction mass storage tanks, Sample collection port available No sampling for hydrogenation reactions	2	1	Low	
11	uenching of Reaction ma	Spillage Exposure Corrosion of Equipment's Fire	Slip trip fall injuries Facility loss Product loss Occupational injuries Business continuation issues	3	2	Medium	Preparing quenching mass in safe method & preparing based on R&D Provided data Controlled addition to control mass temperature and pressure Based on process product mass adding to quenching mass to avoid incidents and accidents Sufficient Colling system and condensing system available Dedicated temperature and pressure gauges available to monitor process parameters	3	1	Low	1)All water media chemicals are using no major hazard for quenching 2)Required to review in HAZOP Study.
12	Layer separation	Spillage Exposure Corrosion of Equipment's Static Fire	Slip trip fall injuries Facility loss Product loss Occupational injuries	4	3	High	Collecting in cleaned layer separation tank Control valves available to control flow of reaction mass Activity carried out by trained employees Level indicators available to monitor level of Separation tank Leakage checking before start operation	4	1	Medium	Effective Training to be provided. Fire detection, alarm system
13	Distillation	Spillage Exposure Corrosion of Equipment's Static Fire	Slip trip fall injuries Facility loss Product loss Occupational injuries	4	3	High	Nitrogen blanketing & Temperature and pressure gauges available to monitor process parameters Dedicated distillation collection tank available Utilities available to control reaction mass temperature and condensation	4	1	Medium	Fire detection, alarm system Work area monitoring and VOC and LEL
14	Strip outs	Spillage Exposure Corrosion of Equipment's Static Fire	Slip trip fall injuries Facility loss Product loss Occupational injuries	3	3	Medium	Nitrogen blanketing & Temperature and pressure gauges available to monitor process parameters Dedicated distillation collection tank available Utilities available to control reaction mass temperature and condensation	3	1	Low	NA
15	Degassing	Spillage Exposure Corrosion of Equipment's	Facility loss Product loss Occupational injuries	3	3	Medium	and accommodate gas generated during production process Dedicated scrubbing system available to control gas generated during reaction Vents kept open condition to avoid gas accumulation during reaction	3	1	Low	Scope to have production block in side vents to be connected to scrubber followed by carbon absorption bed
16	After degassing, Solvent charging for Isolation and reactor starting	Spillage Exposure Static Fire	Facility loss Product loss Occupational injuries	3	3	Medium	Earthing bonding continuation & checking system available Nitrogen blanketing available to avoid fire incident Control addition method following to control reaction mass process parameters	2	1	Low	
17	Before centrifugation, distillation reactor bottom Chock removal under abnormal conditions	Spillage Exposure Static Fire	Facility loss Product loss Occupational injuries	3	3	Medium	1) Using vacuum or Nitrogen pressure to remove Chowk materials	2	1	Low	
18	Mass feeding into Centrifugation (Heavy crystalline material and fine material)	Static fire Spillage	Product loss Occupational injuries	3	3	Medium	1) Using control valves to control flow 2) Using vacuum or Nitrogen pressure to remove Chock materials 3) Using sufficient dia of pipe line to avoid flow of Product 4) Maintain sufficient nitrogen pressure to avoid product Chock	2	1	Low	
19	Centrifuge bag lifting through lodder	Spillage Exposure Static Fire	Facility loss Product loss Occupational injuries Fire	3	3	Medium	1) Using proper load baring lifting equipment which is controlled by operators 2) Using proper hooks to control load to avoid material fall incident 3) Activity Operating by trained employees 5) Periodical preventive maintenance schedule available control equipment abnormal function	2	1	Low	

20	Wet lumps breaking	Spillage Exposure Static Fire	Product loss Occupational injuries Fire	3	3	Medium	Employees using activity based personal protective equipment's Activity performing by trained employees Sufficient ventilation and lighting available to perform activity safely Spill control kit and fire hydrant and fire extinguisher and fire balls available to control fire & spill	3]	Low	Scope to check periodically existing controls
21	Wet material loading to drying systems	Spillage Exposure Static Fire	Facility loss Product loss Occupational injuries Fire	3	2	Medium	1) Using proper equipment to shift and load material sin to drying system by trained operator with adequate personal protective equipment's 2) Keeping equipment clean and drying properly before loading in to system 3) Following nitrogen blanketing	3	1	Low	Scope to check periodically existing controls
22	Drying of wet material	Spillage Exposure Static Fire	Fire Product loss Occupational injuries Fire	4	2	Medium	1) Temperature sensor and interlock between hot water circulation and temp sensor available to control temperature 2) Employees handle activity by using activity based personal protective equipment's 3) Fire hydrant and Fire extinguisher and Fire balls available to control fire 3) Nitrogen blanketing using to crack vacuum& during removing materials	3	1	Low	Effective training to be provided. Provided to review in HAZOP Study.
23	Unloading the dried material	Fire due to unloading into Poly bags and static	Fire Product loss Occupational injuries Fire	4	2	Medium	1) Product hazard based personal protective equipment using 2)Unloading material after reaching ambient temperature 3)unloading started after Vacuum releasing with nitrogen	3	1	Low	1) periodically required to check existing practices and Controls effectiveness
24	Milling the semi & Final dried material	Spillage Exposure Static Fire	Fire Product loss Occupational injuries Fire Business continuation issues	3	2	Medium	Contentious earthing bonding system available to control static energy Fire balls and fire extinguishers ,Fire hydrant system available to control fire	2	1	Low	=
25	Neutralization and collection and packing of Hazardous waste material and Spent MLS	Spillage Exposure Static Fire	Fire Product loss Occupational injuries Fire	3	2	Medium	1)Collecting Hazardous waste in compatible packing materials with adequate personal protective equipment by trained employees 2) Monitoring activity by chemist contentiously 3) Spot exhaust system available to controls fumes 4) AHU System available to maintain clean air at work place 5) Dedicated hazardous waste storage facility available ,Faculty maintained by dedicated environment team round the clock	2	1	Low	periodically required to check existing practices and Controls effectiveness
26	Reactors Cleaning& Confined vessel entry and work at Height	Spillage Exposure Static Fire	Fire Product loss Occupational injuries Fire	3	3	Medium	1) Following work permit system and lock out and tag out system for safe cleaning of Reactors 2) Employees handle activity by using activity based personal protective equipment's 3) Activity monitoring by supervisor contentiously and safety team till completion of work 4) Using Safety belts and Checking work place LEL ,02 level and H2S Levels allowed employees after proper oxygen levels at work place	3	1	Low	Scope to have Tripod to manage emergency evacuation from Reactor periodically required to check existing practices and Controls effectiveness
27	Addition tanks cleaning Transfer line cleaning Centrifuge cleaning	Spillage Exposure Static Fire Fall incident	Fire Product loss Occupational injuries Fire	4	2	Medium	1) Employees using activity based personal protective equipment's 2) Activity performing by trained employees 3) cleaning solution collecting in close loop 4) Spill control kit available to control spill 5) Fire extinguisher ,Fire hydrant and fire balls available to control fire	3	1	Low	periodically required to check existing practices and Controls effectiveness
28	Miller& pulvarizer equipment handling&PCO cleaning	Spillage Exposure Static Fire Fall incident	Spillage Exposure Static Fire Fall incident	3	3	Medium	1) Employees using activity based personal protective equipment's 2) Activity performing by trained employees 3) cleaning solution collecting in close loop 4) Spill control kit available to control spill 5) Fire extinguisher ,Fire hydrant and fire balls available to control fire	2	1	Low	periodically required to check existing practices and Controls effectiveness

				- New York							
29	Product containers cleaning	Spillage Exposure Static Fire Fall incident	Spillage Exposure Static Fire Fall incident	2	2	Medium	1) Employees using activity based personal protective equipment's 2) Activity performing by trained employees 3) cleaning solution collecting in close loop 4) Spill control kit available to control spill 5) Fire extinguisher ,Fire hydrant and fire balls available to control fire	3	1	Low	
30	Product used Filters cleaning	Spillage Exposure Static Fire Fall incident	Spillage Exposure Static Fire Fall incident	3	3	Medium	1) Employees using activity based personal protective equipment's 2) Activity performing by trained employees 3) cleaning solution collecting in close loop 4) Spill control kit available to control spill 5) Fire extinguisher ,Fire hydrant and fire balls available to control fire	2	1	Low	
31	Pharma material used poly bag cleaning	Spillage Exposure Static Fire Fall incident	Spillage Exposure Static Fire Fall incident	4	2	Medium	1) Employees using activity based personal protective equipment's 2) Activity performing by trained employees 3) cleaning solution collecting in close loop 4) Spill control kit available to control spill 5) Fire extinguisher, Fire hydrant and fire balls available to control fire	3	1	Low	
32	Reactor refluxed solvent unloading and transfer to yard	Spillage Exposure Static Fire Fall incident	Spillage Exposure Static Fire Fall incident	3	3	Medium	Using close loop and compatible drums to unloading spent mls Transfer safely to Environment department for safe disposal	2	1	Low	
33	Utility breakdown during reaction Distillation	Spillage Exposure Fire	Spillage Exposure Occupational Injury Facility loss Business continuity Issues	4	3	Medium	Pressure gauges And Temperature gauges available to monitor utility supply to production blocks Monitoring Process parameters contentiously by chemist and shift in charges if any abnormality found in process parameters will take adequate action Immediately Utility preventive maintainece schedule available to prevent break down	3	1	Low	periodically required to check existing practices and Controls effectiveness Utility breakdown alarams required.
34	Reactor abnormal sound observing form inside the reactor during process	Spillage Exposure Fire	Spillage Exposure Occupational Injury Facility loss Business continuity Issues	3	2	Medium	4) Control additions system following based on process parameters 1) Periodical preventive maintenance schedule available 2) Using standard equipment's to avid sudden shutdown 3) Alternative equipment available to transfer materials if Shut down existing equipment	2	1	Low	1) Scope to have Product process safety data.
35	Centrifuge Handling	Spillage Exposure Fire	Spillage Exposure Occupational Injury Facility loss Business continuity Issues	3	3	Medium	1) Product hazard based personal protective equipment using 2) Available Up dated Material safety data sheets 3) R&D team & Technology Transfer team monitoring batch initiation process along with Production team 4) facility selection criteria following for safe batch execution 5) Following product base detoxification methods to detoxify waste 6) R&D development base product process parameters are following thorough BPR 7) Electrical controls lik MCB & ELCB system available to control excess load on system due to abnormality. 8) Interlock system is available.	4	1	Low	1) Scope to have Product process safety analysis data and facility selection base on toxicology data 2) Periodical employees health check up on based product toxicology 3) Found using hydralic system to open centrifuge parts for cleaning and Bag loading scop to have standard seconday guard as secondary protection to avoid fall incident on employees in case of Pneumatic system failure
36	Handling ANFD	Spillage Exposure Fire	Spillage Exposure Occupational Injury Facility loss Business continuity Issues	4	2	Medium	1) Dedicated Facility availble to handle System 2) Equipment handling by using all required personal protective equipments 3) All trained operators handling equipment safely 4) Interlock system is available.	3	1	Low	1)Existing safety control monitoring required periodically
37	Handling PNFD	Spillage Exposure Fire	Spillage Exposure Occupational Injury	4	2	Medium	Following safe procedure for handling and dispsoal Employee using activity based perosnal protective equipments	3	1	Low	1)Existing safety control monitoring required periodically

38	Handling Pulvarizer	Spillage Exposure Fire	Spillage Exposure Occupational Injury	3	3	Medium	Following safe procedure for handling and dispsoal Employee using activity based perosnal protective equipments	3	1	Low	1)Existing safety control monitoring required periodically
39	Handling Sifter	Spillage Exposure Fire	Spillage Exposure Occupational Injury	3	2	Medium	Following safe procedure for handling and dispsoal Employee using activity based perosnal protective equipments	2	1	Low	1)Existing safety control monitoring required periodically
40	Handling Biopolar system	Spillage Exposure	Spillage Exposure Occupational Injury	3	3	Medium	Following safe procedure for handling and dispsoal Employee using activity based perosnal protective equipments	3	1	Low	1)Existing safety control monitoring required periodically
41	Handling Ion Exchage system	Spillage Exposure	Spillage Exposure Occupational Injury	3	2	Medium	Following safe procedure for handling and dispsoal Employee using activity based perosnal protective equipments	2	1	Low	1)Existing safety control monitoring required periodically 2) Ammonia vapor adour to be control.
42	Prodcut change over cleaning using methanol	Spillage Exposure Fire	Spillage Exposure Occupational Injury, Process interuption , Fire & bun injury	4	3	High	1) Following safe procedure for handling and dispsoal 2) Employee using activity based perosnal protective equipments 3) Uasing earthing bonding continuity & Using SS Buckets to shift matierals from one palce to other place 4) Reactors having double earthing bonding system, 5) Earth pits are monitoring contenious 6) Transfering containers with lid (SS Make) using for storing and shifting of method for PCO Cleaning	4	1	Medium	1. Effective Training to be provided. 2. Fire detection, alarm system 3. Work area monitoring and VOC and LEL
43	Handling of Ammonia Gas cylinders	Fall of gas cylinder Leakage of gas from gas cylinders	Ammonia leakage , Cold burns Exposure Occupational Hazard Process interruption Fire & Medical treated or fatal Incident	4	3	High	shfiting of methnol for PCO Cleaning 1)Using fork list with trained employees handling activity 2) Maintaining good house keeping to avoid slip trip fall incident 3) Fork lit having periodical preventive maintenance 4) Gas cylinders are having periodical pressure testing certificates 5)lifting minimum safe height to avoid fall incident & consequeses to fall incident 6)Adequate designed chain pulley with hooks to avoided shift gas cylinder towards gas cylinder usage facility	4	1	Medium	1. Effective Training to be provided. 2. Fire detection, alarm system 3. Work area monitoring and VOC and LEL
44	,	Spillage ,leakage,heat dissipation,highl y body injuries.	Burn skin, incase of direct contact with high temperature surafe in body, slip and fall, Enviorment pollution,	5	4	Extreme	Display boards arranged as HOT SURFACE AREA DO NOT TOUCH to identify that high temperute equipments from rest of the equipments. Use proper PPE kits. Personal are trained to operate the hot oil system.if any leakage use proper tools to arrest. All pipelines are should be insulated properly. working area to be monitoring by trined person.	4	1	Medium	1) Effective training to be provided. 2) Proper PPE kit to be used. 3) Suitable gaskets to be used.

Prepared By	Reviewed By	Approved By
Name:K. Ananda (Dy.Manager)	Name: Lokeswara Duthala (Sr. Manager)	Name: R Elangovan (DGM-EHS)
Sign: 25/05/23	Sign: 4 25 05 23	Sign: Rock 195/29

Hazards = Most severe)	4-Major 5-Catastrophic	medical Work-related restricted work case Work-related lost day case Work-related fatality or disability. (e.g.,	tures) Death or loss in body part)		
Severity Criteria for Occupational Health & Safety Hazards Severity of Consequence (Scale 1 = Least severe to Scale 5 = Most severe)	3-Moderate	Work-related restricted work case Work-related	reatment case (e.g.: small cut (e.g.: very small cut Injury led to (E.g.: Fractures)	medical stop the work)	
Severity Severity of Con-	2-Minor		treatment case (e.g.: small cut	Injury needs medical	assistance
	1-Insignificant	Work-related first aid case Work-related	(e.g.: very small cut)		

		On-site/Off-site significant environmental impact environmental impact environmental impact environmental impact (not easily (containable), may lead to recoverable) may lead to significant statutory notice/fines (high fines, prosecutions and business significance). e.g., a moderate interruption (extreme significance). e.g., spill requiring immediate a major spill which needs immediate containment actions on-site containment actions on-site containment actions site by ERTs/external agencies.
	C	sign (not :0 sign inficance inficance is imn ich on-scies.
	trophi	pact lead t is an ne sign ne sign t for bo
	5-Catastrophic	ite may may ecutior (extrer l whic actions extern:
		On-site/Off-site environmental impact (no recoverable) may lead to s fines, prosecutions and interruption (extreme significa a major spill which needs in containment actions for both o site by ERTs/external agencies.
		On-sit envirc recove fines, interr a maj contai
re)		impact ead to high oderate nediate on-site
st seve	ıjor	may l ce/fines g, a mu g imr ctions
ts 5 = Mo	4-Major	Off-site nental able), / notic nce). e. equiring again and and and and and and and and and an
Aspec Scale		On-site/(environn (contains statutory significar spill re containm by ERTs.
menta		impact On-site/Off-site significant attract environmental impact environmental impact environmental impact environmental impact environmental impact environmental impact (not easily authority (containable), may lead to recoverable) may lead to significant e.g., a statutory notice/fines (high fines, prosecutions and business requiring significance). e.g., a moderate interruption (extreme significance). e.g., spill requiring immediate a major spill which needs immediate containment actions on-site containment actions or-site containment actions for both on-site/off by ERTs.
nviron east se	e	tal in at
ia for E le 1 = L	3-Moderate	ronmen may statutor nificanc spill ctions.
Criter ce (Sca	3-M	envir nable), n of s n sign te ment ac
Severity Criteria for Environmental Aspects isequence (Scale 1 = Least severe to Scale 5 =		On-site environmental impact On-site/Off-site significant (containable), may attract environmental impact environmental impact (not easily attention of statutory authority (containable), may lead to recoverable) may lead to significant (medium significance). e.g., a statutory notice/fines (high fines, prosecutions and business moderate spill requiring significance). e.g., a moderate interruption (extreme significance). e.g., spill requiring immediate a major spill which needs immediate containment actions on-site containment actions for both on-site/off-by ERTs.
Severity Criteria for Environmental Aspects Severity of Consequence (Scale 1 = Least severe to Scale 5 = Most severe)		ental (low ninor
verity (or	Onsite local environm impact (containable) significance). e.g., Few m spills, easily containable.
Se	2-Minor	cal er contair :e). e.g. ly cont.
		site lo bact (nificanc lls, easi
		site On: ow imp
	ınt	on-s
	1-Insignificant	tal imį · e.g., ontaina
	1-Ins	Negligible cenvironmental impact significance). e.g., a spill easily containable.
		Negligible environme significanc spill easily

Prenared By	Cheked By	Approved By
Name::K. Ananda (Dy.:Manager)	Name:Lokeswara Duthala (Sr. Manager)	Name: R Elangovan (DGM-EHS)
Sign: Approved 125/23	Sign: 4-25 (23	Sign: R. M-24/05/22

Shilpa Pharma Lifesciences Limited, Unit 2

Plot No: 33, 33A & 40-47, Raichur Industrial Growth Centre, Chicksugur 584134, Raichur, Karnataka, India

RISK SUMMARY

AO-AO7-Block		Summary of HIRA	of HIRA			Summary of EAIA	of EAIA	
	Worst Ca	Worst Case Impacts	Residual	Residual Impacts	Worst Cas	Worst Case Impacts	Residua	Residual Impacts
KISK/Opportunity Kating	N _o	%	S N	%	No	%	No	%
Opportunity	0	0	0	0	0	0	0	0
Extreme	1	က	0	0	0	0	0	0
High	9	17	0	0	1	17	0	0
Medium	27	77	2	20	4	29	1	17
Low	1	3	28	80	1	17	2	83
TOTAL	35	100	35	100	9	100	9	100

Note: HIRA: Hazard Identification & Risk Assessment, EAIA-Environmental Aspects-Impacts Assessments. Worst Case Risk/Impact: Prior to implementation of existing and additional control measures.

Risk/Impact Level	Risk/Impact Acceptability	Actions Based on Risk/Impact Levels
Low	Ensure controls	Additional controls may be considered as improvement opportunities. An annual review is needed to ensure that the risk levels assigned are not increased over time. Monitor effectiveness of existing controls.
Medium	Must ensure controls	Additional controls for improvement opportunities. Department head's attention is required to maintain the risk levels at this level and not to increase over time. Monitor effectiveness of existing controls.
High	Must act	High risk level must be reduced by implementing additional risk controls before work commences. The High risk shall be controlled by using substituted/engineering controls before commencing work. Department head's intervention is required before commencing work.
Extreme	Cannot accept	The Extreme risk should be avoided as far as possible. If avoidance is not possible, control the Extreme risk by using substituted and engineering controls before commencing work. Site management's intervention is required before commencing work.

Prepared By	Cheked By	Approved By
Name::K. Ananda (Dy.Manager)	NameLokeswaga Duthala (Sr. Manager)	Name: R Elangovan (DGM-EHS)
Sign: Ctthronder 25/85/23	Sign: 4 Sign:	Sign: R. Marelos 120